

NEXT100-PMT

System Requirements

- pressure resistance 15.4 barg ext press.
- pressure isolation (window break) <2 barg
- radiopurity <50mBq total
- heat dissipation <10 deg C
- ease of maintenance
- minimum cost